

West tower caisson

Concrete anchor blocks


Steel girders under roadbed

This section fell in one piece

Concrete roadbed

Supporting girders (typically attached to remainder of roadbed)

East tower caisson



Fred Matamoros/The News Tribune

LETTING GALLOPING GERTIE LIE: Map shows where Galloping Gertie, the first Narrows Bridge, lies at the bottom of The Tacoma Narrows after collapsing in a windstorm Nov. 7, 1940. The bridge's remains are on local and national historic registers. Bridge builders vow they won't disturb the remains when they build a second Narrows Bridge.